



Forum: LASER

Topic: canon ir 6000

Subject: Re: canon ir 6000

Enviado por: jefersonlisik

Enviado em: 10/10/2013 09:01:56

E733

Main cause The connector has poor contact. The DC controller PCB is faulty. Mode of Detection 0001
The main controller PCB has detected an error in the communication between the DC controller PCB
and the main controller PCB. CLEAR>ERR). printer boards (accessories) and the main controller
PCB.