



Forum: LASER

Topic: RESET LEX E352DN

Subject: Re: RESET LEX E352DN

Enviado por: Visitante

Enviado em: 05/08/2010 16:33:01

Citando:

Neto25 escreveu:

935 SERVICE PRINthead ERROR,

CONHECE ESSE ERRO?

Olá! Listagem de erros conforme manual. Ve se ajuda alguma coisa

Printhead service errors

931.00 No first hsync

931.01 No first hsync

932.00 Lost hsyncs

932.01 Lost hsyncs

933.00 Printhead boost signal failure

935.10 Printhead sweep error, swept through Hz range without finding the resonant frequency

935.11 Printhead sweep error, autosweep hw state

935.12 Printhead sweep error, coarse sweep state

935.13 Printhead sweep error, init fine sweep state

935.14 Printhead sweep error, fine sweep state

935.15 Printhead sweep error, check prelim amp state

935.16 Printhead sweep error, enable amp Kp state

935.17 Printhead sweep error, amp Kp failed to converge

935.18 Printhead sweep error, enable amp Ki state

935.19 Printhead sweep error, amp Ki failed to converge

935.20 Printhead sweep error, enable offset controller state

935.21 Printhead sweep error, load scan regs state

935.22 Printhead sweep error, fwd and rev capture times differ by too much

935.23 Printhead sweep error, check sweep accuracy state

935.24 Printhead sweep error, reserved

935.25 Printhead sweep error, detected resonant frequency out of expected range

935.26 Printhead sweep error, timed out waiting for end of sweep

Transport motor service errors