



Forum: JATO DE TINTA

Topic: HP DESKJET 3550

Subject: Re: HP DESKJET 3550

Enviado por: jcg

Enviado em: 09/06/2011 08:57:08

verifique a fita ecoder e o sensor dela tambem!!!!!!!

abracos.....