



Forum: LASER

Topic: HP LaserJet Pro 200 color MFP M276NW - ERRO 50.7 - SOLUCIONADO

Subject: Re: HP LaserJet Pro 200 color MFP M276NW - ERRO 50.7

Enviado por: SIMIONATO

Enviado em: 22/01/2015 14:16:30

Boa tarde Arx, nunca peguei este problema
mas achei estas referências, espero que ajude.

50.X FUSER ERROR A fuser error has occurred.

X Description:

- 1 Low fuser temperature
- 2 Fuser-warmup service
- 3 High fuser temperature
- 4 Faulty fuser
- 7 Fuser pressure release mechanism failure
- 8 Low fuser temperature (subthermistor)
- 9 High fuser temperature (subthermistor)

Simionato