



Forum: LASER

Topic: Lexmark C500 dando Tray 1: NO SVC L1 ERROR

Subject: Re: Lexmark C500 dando Tray 1: NO SVC L1 ERROR

Enviado por: oleandrosousa

Enviado em: 19/08/2019 16:55:36

Erro no scan motor , desmonta e limpa novamente !!