



Forum: LASER

Topic: (Error 936: Service Transport Motor) Lexmark x464

Subject: Re: (Error 936: Service Transport Motor) Lexmark x464

Enviado por: Alloc

Enviado em: 08/04/2020 22:31:19

Retire todas as engrenagens, limpe tudo (engrenagens e eixos). Passe graxa branca nos eixos e monte.