



Forum: MULTIFUNCIONAL

Topic: Vida útil fusor Samsung ML 3560 - SOLUCIONADO

Subject: Re: Vida útil fusor Samsung ML 3560

Enviado por: Visitante

Enviado em: 24/07/2014 15:22:20

Acima de 150.000 páginas

Arquivo anexado: 

2014-07-24_15-19-12.jpg (155.17 KB)

Consumable Parts	Retard Roller	Up to 150,000 Pages
	Transfer Roller	Up to 150,000 Pages
	Fuser Assembly	Up to 150,000 Pages
	Toner Sensor	Yes(dot counting)
	Toner Type	Non-Magnetic toner
	Toner Initial	6,000 pages@ISO 5% coverage
	Toner sale	6,000 or 12,000 pages@ISO 5% coverage
Optional Parts	Optional Tray	Paper Capacity : 500 Sheets
	Wired NPC	Ethernet 10/100 base TX
	(ML-3560/ML-3561N : Optional ML-3560 : Basic)	Protocols : TCP/IP, SPX/IPX, Ethertalk, SNMP, HTTP1.1, DLC/LLC 8MB RAM Buffer for faster graphics performance 2MB Flash Memory for upgrade Throughput : 200 ~ 300K TCP/IP