



**Forum: LASER**

**Topic: Sharp AL-2040**

**Subject: Re: Sharp AL-2040**

Enviado por: valmiroliver

Enviado em: 19/11/2015 13:24:33

Tente tambem limpar a corona(corotron de tranferencia) Boa sorte!